

**Appendix C**  
**Photograph Log**





# Photograph Log

**Company:** St. Louis Composting, Inc.

**Facility Name:** Valley Park

**Address:** 39 Old Elam Avenue, Valley Park, MO  
63088

## Photo #1

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing North looking at the new filter socks.



## Photo #2

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing North-west looking at new filter socks.



## Photo #3

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing East looking at the labeled Storage Locker #1.







# Photograph Log

**Company:** St. Louis Composting, Inc.

**Facility Name:** Valley Park

**Address:** 39 Old Elam Avenue, Valley Park, MO  
63088

## Photo #4

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing East looking at the labeled  
Storage Locker #2.



## Photo #5

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing East looking at the labeled  
Storage Locker #3.



## Photo #6

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing North looking at the labeled  
Storage Locker #4.







## Photograph Log

**Company:** St. Louis Composting, Inc.

**Facility Name:** Valley Park

**Address:** 39 Old Elam Avenue, Valley Park, MO  
63088

**Photo #7**

**Photographer:** Tiffany Emmett

**Date:** November 7, 2016

**Description:** Facing East looking at the labeled  
Lubrication Station.



